

SAFETY ALERT

DATE: 23 April 2002

SUBJECT: SECOND NOTICE: SAFETY WIRING – LINK TILT CYLINDER GUARD

SERIAL NUMBERS: All

DISCUSSION: In March 2002, CANRIG released Safety Bulletin 73. Subsequent to this

release, an accident occurred on a rig, where the Link Tilt guard fell off the Top

Drive and struck an employee situated on the rig floor.

It is absolutely imperative that the below instructions are being followed and the guard restraining system is being upgraded to include the specification as found

on the attached drawing.

RECOMMENDATION:

Check each link tilt guard for proper installation of two 1/8" safety restraint wires as per attached drawing. Please note that to ensure cables do not become frayed at the guard tie-off point, this tie-off point on the guard should be on the side, rather than on top.

Further, check that the four retaining bolts holding the guard in position are in place and safety wired as per the attached drawing. If these bolts are not drilled for safety wiring, contact CANRIG and proper bolts will be provided to you. If any bolt or safety wire is missing or not applied as outlined on attached dwg, it should be rectified immediately, or the guard should be removed until it can be properly installed. Removing the guard will expose the stainless steel tubing and will increase the potential of a hydraulic leak.

The following parts and material may be necessary to bring the guard restraining system into compliance:

- 8 feet of 1/8" safety wire (CANRIG part number M10022), cut into 4 equal length and eight ferrules (M19-3006-010), to make restraint cables.
- 6 feet of 1/16" safety wire (CANRIG part number M19-3009-010) and four ferrules (M21-2000-010), for wiring the 1/4" retaining bolts
- Crimping tool (LOCOLOC No.0 (available from CERTEX), or equiv.)
- Drill and 3/16 drill bit (in the event the hole has to be re-drilled on the side of the guard)

If you would like CANRIG to perform the above mentioned checks or modifications or if you have any questions regarding implementation of this bulletin, please contact the person listed below.

When in doubt, do not hesitate to contact CANRIG and ask questions.

INFORMATION:

For further information contact:

Field Operations Manager
Canrig Drilling Technology Ltd.

14703 FM 1488

Magnolia, Texas 77354 Phone: 281.259.8887 Fax: 281.259.8158



Engineering Bill of Material


AY11262 Part:

Description: LINK TILT ASSY, 650 TON, 2 SPD

Eng ID: 0 Drawing ID: AY11262 Rev No: B

| Drawing | Drawing ID: AY11262 | | Rev No: B | | | |
|---------|---------------------|-------|---------------------------|--------|---|--|
| Item | Qty | Units | Part ID | Eng ID | Description | |
| | | | | | | |
| | | | | | | |
| 01 | 1.00 | EA | F451JSJ9080808-44.79-X-42 | 0 | HOSE ASSY, 1/2, SWV STR, 90° SHT, 44.79 | |
| 02 | 1.00 | EA | F451JSJS080808-30.8-X-28 | 0 | HOSE ASSY, 1/2, SWV STR, SWV STR, 30.8 | |
| 03 | 1.00 | EA | F451JSJS080808-28.75-X-26 | 0 | HOSE ASSY, 1/2, SWV STR, SWV STR, 28.75 | |
| 04 | 4.00 | EA | F451JSJS080808-24.8-X-22 | 0 | HOSE ASSY, 1/2, SWV STR, SWV STR, 24.8 | |
| 05 | 2.00 | EA | 594-02-6 | | LUG, ELEVATOR LINK, 750 TON | |
| 06 | 2.00 | EA | 594-05-0 | | PIN, 1.375 DIA, 3.62 LG, HEAD ONE END | |
| 07 | 1.00 | EA | 594-07-0 | | MANIFOLD, HYDRAULIC, LINK TILT | |
| 08 | 2.00 | EA | 689-12-0 | | RETAINER, LINK TILT | |
| 09 | 2.00 | EA | 689-14-0 | 0 | CYL, HYD, BORE 3 1/4, ROD 2, STRK 47.94 | |
| 09A | 0.00 | EA | H18-3220-01B | | CYLINDER SEAL KIT | |
| 09B | 0.00 | EA | H19-1004-010 | | CYLINDER ROD EYE | |
| 09C | 0.00 | EA | M04-1000-020 | | BEARING, PLAIN RADIAL | |
| 09D | 0.00 | EA | M11-1022-010 | | RETAINING RING, INTERNAL | |
| 10 | 1.00 | EA | 689-16-0 | | MOUNT, FLOW DIVIDER, LINK TILT | |
| 11 | 2.00 | EA | 689-19-0-500 | 0 | HYD TUBE, 1/2, LINK TILT, 500 | |
| 12 | 2.00 | EA | 689-20-0 | | GUARD, HYDRAULIC TUBE, LINK TILT, 45.75 | |
| 13 | 1.00 | EA | 919-11-0 | | UPPER SUPPORT LUG LINK TILT | |
| 14 | 1.00 | EA | H04-1012-010 | | VLV, HYD, FLOW DIVIDER, INLINE, SAE-8 | |
| 15 | 2.00 | EA | H15-090109B-08 | | PLUG, SOC HEX, 1/2 ORB | |
| 16 | 7.00 | EA | H15-520220-08-08 | | ELL 90°, MALE 1/2 ORFS, MALE 1/2 ORB | |
| 17 | 1.00 | EA | H15-520701-08 | | ELL 90°, BULKHEAD, MALE 1/2 ORFS | |
| 18 | 1.00 | EA | H15-520118-08 | | LOCKNUT, BULKHEAD 1/2, 13/16-16UNF | |
| 19 | 4.00 | EA | H25-1002-010 | | CLAMP, SINGLE, 1/2 IN DIA | |
| 20 | 8.00 | EA | M19-3006-010 | | FERRULE, 1/16, OVAL, ALUMINIUM | |
| 21 | 72.00 | IN | M21-2000-010 | | WIRE ROPE, 1/16, 7 x 7, STAINLESS | |
| 22 | 10.00 | EA | HH-0250NC-0175-GR8-W | | CAPSCR, HEX HD, 1/4-20UNC x 1.75, GR8 | |
| 24 | 4.00 | EA | SH-0375NC-0125-W | | CAPSCR, HEX SOC HD, 3/8-16UNC x 1.25 | |
| 25 | 2.00 | EA | SH-0312NC-0500 | | CAPSCR, HEX SOC HD, 5/16-18UNC x 5.00 | |
| 26 | 3.00 | EA | SH-0312NC-0100-W | | CAPSCR, HEX SOC HD, 5/16-18UNC x 1.00 | |
| 27 | 2.00 | EA | LN-0312NC-GR8 | | LOCKNUT, 5/16-18UNC, GR8 | |
| 28 | 2.00 | EA | LN-0250NC-GR8 | | LOCKNUT, 1/4-20UNC, GR8 | |
| 29 | 5.00 | EA | FW-0312-A | | WASHER, F, 5/16, PLAIN, TYPE A | |
| 30 | 8.00 | EA | LW-0250-ET | | LOCKWASHER, 1/4 EXTERNAL TOOTH | |
| 31 | 1.00 | EA | H15-520320-08 | | ELL 45°, MALE 1/2 ORFS, MALE 1/2 ORB | |
| 32 | 8.00 | | M19-3009-010 | | FERRULE, 1/8, OVAL, ALUMINIUM | |
| 33 | 96.00 | IN | M10022 | | WIRE ROPE, 1/8, STAINLESS, 7 X 19 | |

Printed: 4/24/2002 Page 1 of 1



| Top Drive Product Bulletin | |
|----------------------------|------------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | This page intentionally lett blank |
| | This page intentionally left blank |
| | This page intentionally lett blank |
| | This page intentionally left blank |
| | This page intentionally lett blank |