

Applies To: 275 Ton Top Drive

August 3, 2012

Product Bulletin # 123



## Replacement of Lower Well Control Valve Anti-Rotation Bracket

## Introduction

This safety bulletin addresses Canrig 275 ton top drives (Model 6027) that have been equipped with a remotely-operated lower well control valve (LWCV). The LWCV actuator has an anti-rotation bracket that is mounted on the side of the LWCV. During a routine inspection, it was discovered that this LWCV anti-rotation bracket (Canrig Part # DT16711) was cracked as shown in the picture below. This creates a potentially dangerous situation in which the bracket could break and fall to the rig floor.

## Recommendation

The bracket should be visually inspected for cracks as soon as possible. This inspection should be included as part of your routine top drive inspection program. If a crack is found, the bracket should be removed from service for repair or replacement.

Figure 1 on page 2 shows a crack on the old anti-rotation bracket (Part # DT16711). This bracket is 1/2" thick. The replacement bracket (Canrig Part # DT31736) is made using 1" thick plate and uses stronger material. (See Figure 2 on page 2.) This replacement bracket may be ordered from the Canrig Sales department.



Product Bulletin # 123




Figure 1: Cracked LWCV Anti-Rotation Bracket (Part # DT16711)

Top Drive Model	Old Anti-Rotation Bracket	Replacement Anti-Rotation Bracket
6027	DT16711	DT31736




Figure 2: Old and New LWCV Anti-Rotation Brackets