Safety Bulletin		
No: SB036	Rev: 1	Date: 01 Sept 2010

Retrofit – Add Torque Limiting Mechanism to Casing Drive System Link Tilt Assembly



Tesco Corporation 5616 – 80th Street SE Calgary, AB. T2C 4N5 Phone: (403) 723-7902 Fax: (403) 723-7826 www.tescocorp.com

BACKGROUND INFORMATION:

In the event of a Casing Drive System (CDSTM) actuator bearing failure that results in complete bearing seizure, the CDS link tilt hanger and links have the potential to rotate with the top drive quill if the CDS anti-rotation bracket fails. To address this safety concern, TESCO has created a retrofit kit to add a torque limiting breakaway system on the CDS link tilt assembly. The CDS link tilt breakaway system addresses the hazard of a rotating CDS link tilt system by providing a mechanical "fuse" that will fail before the CDS anti-rotation bracket.

A second version of the shear pin made of 4140 steel was introduced to replace the previous brass shear pin, after extensive field tests in April 2010.

A retrofit kit (TESCO part number 860197) has been created with the additional parts required to retrofit existing link tilt carriers. Please refer to the attached illustration I-860197. If the retrofit kit is used in conjunction with non-standard length anti-rotational brackets, contact your local TESCO Service Center and TESCO Engineering for additional guidance before implementation.

Third-party customers that own CDS tools must return the effected components to the local TESCO Service Center to have the required modifications completed.

AFFECTED PRODUCT:

All CDS link tilt assemblies manufactured prior to Dec. 31, 2007.

Affected Part No.	Description
540339, 16057	Carrier, Machined, Link Tilt Hanger, CDS
820052, 15258	Cap, Top, Actuator, CDS

ACTION REQUIRED:


Refer to attached drawing I-860197.

- 1. Modify carrier (p/n 540339 or 16057) as per drawing 1170004 (drawing attached);
- 2. Modify top cap (p/n 820052 or 15258) as per drawing 860183 (drawing attached);
- 3. After the modification for both carrier and top cap, reassemble the link tilt kit by adding all the parts listed in drawing 860197;
- 4. See note 2 in drawing 860197, if the modified top cap interferes with actuator nameplate, replace the old nameplate with p/n 860184 using 4 screws p/n 14439.

A detailed work instruction WI-860197 giving step-by-step instructions to complete the modifications is also attached below.

Contact your local TESCO Parts and Service Center for further information regarding this bulletin and or supply of affected components noted above.

1	RPM	100901	126-0011	Included reference to new shear pin material, using retrofit kit with non-standard length anti-rotational brackets
0	RPM	070415		Issued for reference
Rev:	By:	Date:	ICD/ECN:	Description:



- Ensure Socket Head Capscrews are 4-5 turns loose, and adjust Jacking Set Screws (item 1) to permit Carrier Installation.
 Apply Loctite 243 to items 1. Adjust until Carrier rotates without binding.
 Turn in Set Srews additional 1/4 turn clockwise each.

- Apply Loctite 243 to Socket Head Capscrews and torque to 25 ft-lbs each.
 Confirm free rotation of Carrier.
- Adjust Capscrews and Set-screws if required.

Note 2: If Top Cap rework interferes with Actuator Nameplate, remove Nameplate and install new Nameplate (Part # 860184) using Drive Screws (Part # 14439, quantity 4).

Rev. By Date ICD/ECN# Description LJW 071114 086-0063 Issued for manufacture

EC 100723 126-0011 Item 9 material changed from brass to steel



1	RPM	100901	126-0011	Included reference to new shear pin material, using retrofit kit with non-standard length anti-rotational brackets
0	RPM	070415		Issued for reference
Rev:	By:	Date:	ICD/ECN:	Description:

Parts List



Part # 860197

Drawing # I-860197

Rev. 1 Page 2 of 2

File # I-860197.xls


Refer: 1 Illustration

Drawing Title: Retrofit Kit, Link Tilt, Torque Limiting, CDS


Item #	Tesco#	Qty	Description	Doc#
1	14573	2	Screw, Set, Skt Drive, Cup Pt, 1/2"-13UNCx1"	
2			Not used	
3	10632	2	Washer,Flat,Type A,Narrow,3/8",Hardened,Pld	
4	1500003	1	Bearing, Thrust, Link Hanger, Torque Limiting, CDS	1500003
5	1500004	1	Nylatron GS, 3/16 x 1 1/2 x 43 3/4	
6			Not used	
7	1500002	1	Carrier, O-Ring, Link Hanger, Torque Limiting, CDS	1500002
8	510529	1	Ring,Retaining,External,13.500"ID Shaft,0.187"Thk	
9	5001684	1	Pin,Shear,Steel,CDS,Torque Limiting	5001684
10	830021	1	Stop, Torque, Torque Limiting, CDS	830021
11	8626	2	Screw,Cap,Hex Hd,3/8"-16UNCx1-1/2",Gr8,Pld,Dr Hd	SEE 55251107
12			Not used	
13	1500005	1	O-Ring,N70-458,14.475"IDx0.275"Dia	
14			Not used	
15	1116	1	Fitting, Grease, Str, Short, 1/4"-28Tpr Thd (SAE-LT)	

26-07-10 CHKD: APPR'D:

1	RPM	100901	126-0011	Included reference to new shear pin material, using retrofit kit with non-standard length anti-rotational brackets
0	RPM	070415		Issued for reference
Rev:	By:	Date:	ICD/ECN:	Description:



1	RPM	100901	126-0011	Included reference to new shear pin material, using retrofit kit with non-standard length anti-rotational brackets
0	RPM	070415		Issued for reference
Rev:	By:	Date:	ICD/ECN:	Description:



1	RPM	100901	126-0011	Included reference to new shear pin material, using retrofit kit with non-standard length anti-rotational brackets
0	RPM	070415		Issued for reference
Rev:	By:	Date:	ICD/ECN:	Description:



Tesco Corporation 5616 – 80th Avenue SE Calgary, Alberta T2C 4N5 Phone: (403) 723-7902

Fax: (403) 723-7826 Web: www.tescocorp.com

Work Instruction

WI No: WI-860197 Rev: 0 Date: July 23, 2010

Description: Modification Instructions For The CDS Torque

Limiting Link Tilt Retrofit Kit

Originator: Ryan Miller Checked: Approved:

Date: July 23, 2010 Date:

1 Scope

This document covers the additional machining required to convert an existing casing drive system (CDS) actuator top cap and an existing CDS link tilt hanger carrier into the torque limiting version.

2 Tools and Equipment Required

N/A

3 Safety Precautions

The actuator is under spring pressure. Use extreme caution when assembling or disassembling the actuator.

Perform a Job Safety Analysis – JSA before assembling and disassembling the actuator. Ensure all hazards and risks are included in the JSA and discussed with personnel involved prior to start of maintenance job.

Use appropriate Personal Protective Equipment according to hazards found in JSA.

Capture any change in maintenance procedures/tools in JSA and remind personnel involved in maintenance jobs prior to start of maintenance jobs.

4 Procedure

4.1 CDS Actuator Top Cap Modifications:

Reference drawing: 860183

- 1. Obtain an existing top cap, part #15258 (Mark 1) or part #820052 (Mark 2).
- 2. Add the retaining ring groove (Ø12.927" × 0.209") as shown in drawing 860183.
- 3. Add the two $\emptyset 5/16" \times 0.494"$ deep drilled holes as shown in drawing 860183.
- 4. MPI machined areas. Any indications found will be brought to the attention of TESCO Engineering.
- 5. Zinc phosphate and oil machined areas by immersion process to obtain 1000 3000 mg per sq. ft. coverage after MPI.

Note: If the top cap is removed from the actuator to perform this modification, the actuator shall be retested as per EM000145, Post Assembly Actuator Tests #1 through 5.

1	RPM	100901	126-0011	Included reference to new shear pin material, using retrofit kit with non-standard length anti-rotational brackets
0	RPM	070415		Issued for reference
Rev:	By:	Date:	ICD/ECN:	Description:

4.2 CDS Link Tilt Hanger Carrier Modifications:

Reference drawing: 1170004

- 1. Obtain an existing link tilt hanger carrier, part #540339 or part #16057.
- 2. Remove the bolt block by machining as shown in drawing 1170004. Any sharp edges are to be blended out. Torch cutting is not permitted.
- 3. Drill and tap the six $\emptyset 3/8$ " 16 UNC × 1" deep holes as shown in drawing 1170004.
- 4. Drill and tap the $\emptyset 1/4$ " NPT × 3" deep hole as shown in drawing 1170004.
- 5. Cross drill the $\emptyset 1/4$ " \times 1-3/8" deep hole as shown in drawing 1170004.
- 6. Open up the bore of the carrier to Ø13.60" as shown in drawing 1170004.
- 7. Open up the top 1.29" (REF) of the bore to Ø15.00" as shown in drawing 1170004.
- 8. Open up 1.53" of the bore to Ø13.93" as shown in drawing 1170004.
- 9. Spot face the bottom 0.25" of the bore to Ø15.63"
- 10. Roller burnish or polish the bottom spot face to 20 μ inch as shown in drawing 1170004.
- 11. MPI machined areas. Any indications found will be brought to the attention of TESCO Engineering.
- 12. Paint TESCO yellow as per TESCO specification STD0009.

1	RPM	100901	126-0011	Included reference to new shear pin material, using retrofit kit with non-standard length anti-rotational brackets
0	RPM	070415		Issued for reference
Rev:	By:	Date:	ICD/ECN:	Description: