| | Safety B | | Tesco Corporation | |
|---|----------|--|-------------------|--|
| • | • | ^{11 Dec 2008} Drive – Grabber Lift Interference | TESCO | 6204 – 6A Street SE Calgary, AB. T2H 2B7 Phone: (403) 692 5700 <u>www.tescocorp.com</u> |

BACKGROUND INFORMATION:

A potential mechanical interference risk has been identified wherein the driller side upper elevator link eye is able to come into contact with the grabber lift accumulator guard. The area of contact is shown in Figure 1.




Figure 1 – Location of elevator link eye contact.

This interference may occur if the elevators are allowed to contact the rig floor or other obstructions and the elevator links are pushed into the bottom of the load collar horns while the elevator links are tilted forward. Other factors that may contribute to this interference include,

- Incorrectly positioned elevator link clamps allowing excessive tilting of the elevator links.
- The use of links with large eyes.

It has been brought to TESCO's attention that a number of units may have been modified in the field by removing a portion of the accumulator guard to accommodate the range of motion of the elevator link eyes. This practice can result in a serious safety risk as, in addition to providing protection to the accumulator, the guard also serves as a secondary retention mechanism to protect against dropped object incidents. In one instance the portion of guard removed was sufficient to allow the accumulator to fall through the guard and resulted in a dropped object incident.

To eliminate the potential for mechanical interference TESCO has relocated the grabber lift manifold and accumulator to a position above the elevator link retainers as shown in Figure 2. Further, a safety cable has been implemented as a positive secondary retention for the accumulator in its new location.

TESCO recommends that all EXI model top drives have the grabber lift manifold and accumulator retrofitted to this new location.




Figure 2 – Relocated Accumulator, Clamp Bracket and Safety Cable

AFFECTED PRODUCT:

TESCO model 350HXI600 top drives with the following unit numbers require relocation of the grabber lift manifold and accumulator and the addition of accumulator clamp bracket and safety cable:

521, 537, 541, 594, 617, 620, 621, 625, 659, 675, 676, 687, 688, 707, 709, 710, 711, 712

ACTION REQUIRED:

Please contact your local TESCO representative who will perform the following repairs, including relocation of the grabber lift accumulator, addition of a clamp bracket and safety cable, and re- routing of the oil cooler hoses to provide clearance for the new accumulator position.

Note: If for some reason an immediate full repair is not possible, TESCO recommends, as a minimum, the addition of the safety cable to the accumulator until such time that the full repair can be made.

Relocation of grabber lift manifold and accumulator:

- 1. Remove accumulator guard and manifold/accumulator assembly.
- 2. Layout locations for grabber lift manifold mount as shown in Drawing 820148 Rev 2 (attached).
- 3. Drill and tap new manifold mounting holes in accordance with Drawing 820148 Rev 2 (attached).
- 4. Install clamp bracket and safety cable following instructions below and re-install grabber lift
 - manifold/accumulator assembly in accordance with illustration I-840048 Rev 5 or higher (attached).

Addition of Clamp Bracket and Safety Cable:

- 1. Using 3/8"-24UNF x 1/2" fastener (TESCO PN 1390065), install safety cable (TESCO PN 1390064) onto accumulator as shown in Illustration I-840048 Rev 5 or higher (attached).
- 2. Install accumulator clamp bracket (TESCO PN 1030251) between manifold and upper grabber leg as shown in Illustration I-840048 Rev 5 or higher (attached).
- Install accumulator clamp (TESCO PN 1030253) as shown in Illustration I-840048 Rev 5 or higher (attached).
- 4. Using manifold mounting bolt, secure safety cable as shown in Illustration I-840048 Rev 5 or higher (attached).
- 5. Ensure all hardware is installed using thread locking compound and is safety wired or retained with cotter pins as shown in I-840048 Rev 5 or higher (attached).

Re-Routing of Cooler Fan Motor Hoses:

As shown in Figure 3 the cooler fan motor hoses need to be re-routed to avoid the potential for catching on the relocated manifold block when the pipe handler is rotated. Figure 4 shows the new hose routing for the motor supply and return lines that should be implemented to avoid catching.




Figure 3 – Original fan motor hose routing






Figure 4 – Modified hose routing towards front of cooler

Contact your local TESCO Parts and Service Center for further information regarding this bulletin and/ or supply of affected components noted above.





| ITEM NO | QTY. | PART NO. | | DESCRIPTION | | | | | |
|----------|------------|------------------------|---|--|-------------|---------|-------|--------|-----------------|
| 1 | 1 | 770634 | MANIFOLD A | DLD ASSEMBLY, 10-Station, 350-EXI-600 | | | | | |
| 2 | 1 | 810501 | BRACKET, AL | BRACKET, AUXILARY MANIFOLD, 350 EXI 600 | | | | | |
| 3 | 8 | 8626 | SCREW,CAP, | SCREW,CAP,HEX HD,3/8"-16UNCX1-1/2",GR8,PLD DR HD | | | | | |
| 4 | 15 | 7135 | WASHER,LO | WASHER,LOCK,HELICAL SPRING,3/8",ALLOY,PLD | | | | | |
| 5 | 8 | 3687 | WASHER,LOCK,HELICAL SPRING,5/8",ALLOY,PLD | | | | | | |
| 6 | 8 | 730959 | | SCREW,CAP,HEX HD,5/8"-11UNCX1-3/4",GR8,PLD,DR HD | | | | | |
| 7 | 1 | 820189 | | MBLY, GRABBER LIFT MANIFOLD, EXI / HXI | | | | | |
| 8 | 1 | 1090073 | - Î | LD, MINI BOOSTER, HC3 | | | | | |
| 9 | 7 | 1030252 | SCREW,CAP, | | | " GR8 P | D DR | HD | |
| 10 | 1 | 1030251 | | | | | | | |
| 10 | 1 | 1100120 | | MOUNT,CLAMP,ACCUMULATOR,GRABBER LIFT,250-HXI-700 | | | | | |
| 12 | 3 | 1030253 | | GUARD, INTENSIFIER, GRABBER, EXI/HXI | | | | | |
| 12 | - | | | AMP,EXHAUST,3-1/2"IDX3/8"-16UNC,DR THD,YELLOW | | | | | |
| | 4 | 1390065 | | REW,CAP,HEX HD,3/8"-24UNFX1/2",GR8,PLD,DR HD | | | | | |
| 14 | 4 | 3690 | | ASHER,LOCK,HELICAL SPRING,HI-COLLAR,3/8",BLACK | | | | | |
| 15 | 4 | 8763 | 1 | REW,CAP,SKT HD,3/8"-16UNCX1",DR HD | | | | | |
| 16 | 1 | 720222 | GAUGE,LIQ F | | | | | | |
| 17 | 1 | 7353 | GAUGE, LIQ I | | | | | | |
| 18 | 7 | 0022 | | ALVE,CONTROL,1/4"NPT,C/W REV FLOW FREE CHECK | | | | | |
| 19 | 10 ft | 15473 | SLEEVE,HOS | | | | | | |
| 20 | 1 | 0389 | | CAP, QUICK DISCONNECT, NIPPLE, 78-SER, 1" | | | | | |
| 21 | 1 | 0387 | PLUG, QUICK | PLUG, QUICK DISCONNECT, COUPLER, 78-SER, 1" | | | | | |
| 22 | 2 | 0411 | DISCONNEC | DISCONNECT,QUICK,COUPLER,74SERIES,3/8"X3/8"FNPT | | | | | |
| 23 | 2 | 3461 | CAP, QUICK I | CAP, QUICK DISCONNECT, COUPLER, 74-SER, 3/8" | | | | | |
| 24 | 2 | 0418 | QUICK DISCO | QUICK DISCONNECT, NIPPLE, 3/8"X3/8"FNPT, 74 SERIES | | | | | |
| 25 | 2 | 3460 | CAP, QUICK DISCONNECT, NIPPLE, 74-SER, 3/8" | | | | | | |
| 26 | 1 | 2008 | DISCONNEC | DISCONNECT, QUICK, NIPPLE, 78 SERIES, 1"X1"FNPT | | | | | |
| 27 | 1 | 2895 | | DISCONNECT,QUICK,COUPLER,78SERIES,1"X1"FNPT | | | | | |
| 28 | 1 | 1100093 | | ACCUMULATOR, 1PT, 3000-PSI, #12FORB | | | | | |
| 29 | 2 | 1390064 | | CABLE,SAFETY,7X7WIRE ROPE,1/8"DIA,3/8"ID TAB X 6"LONG X 3/8"ID TAB | | | | | |
| 30 | 2 | 1091 | | PIN,COTTER,1/8"ODX1"LG,PLD | | | | | |
| 31 | 2 | 4333 | | NUT,HEX,LOCK,NYLON,3/8"-16UNC,GR8,PLD | | | | | |
| 32 | 1 | 910012 | | MOUNT, CLAMP, 2ND ACCUMULATER, GRABBER LIFT, 350-EXI-600 | | | | | |
| 101 | 1 | 820282 | | Fitting,Hyd,Str,#6MJICx#16MNPT | | | | | |
| 102 | 2 | 0353 | | FITTING,HYD,90°ELB,#4MJICX#4FJIC | | | | | |
| 102 | 9 | 0199 | | | | | | | |
| 103 | - | 2788 | | | | | | | |
| | 1 | | | FITTING, HYD, 90°ELB, #6MJICX#8MORB | | | | | |
| 105 | 1 | 12128 | | ITTING, HYD, TEE, #6MJICX#6MJICX#6MORB-BR | | | | | |
| 106 | 3 | 0337 | | FITTING, HYD, STR, #6FJICX#4MJIC | | | | | |
| 107 | 2 | 0239 | | FITTING,HYD,STR,#6MNPTx#4MNPT | | | | | |
| 108 | 1 | 0352 | | FITTING,HYD,90°ELB,#6MJICX#6FJIC-SWVL | | | | | |
| 109 | 14 | 1497 | | FITTING,HYD,STR,#6MJICX#6MORB | | | | | |
| 110 | 1 | 0327 | | FITTING,HYD,STR,#4FNPTX#6FJIC | | | | | |
| 111 | 1 | 12303 | | FITTING,HYD,90°ELB,#8MJICx#6MORB | | | | | |
| 112 | 2 | 12304 | FITTING, HYD | FITTING,HYD,90°ELB,#4MJICX#8MORB | | | | | |
| 113 | 2 | 0292 | FITTING,HYD |),STR,#6MJ | ICX#6MNPT | | | | |
| 114 | 5 | 12291 | FITTING,HYD |),45°ELB,#6 | MJICX#6MO | RB | | | |
| 115 | 2 | 0310 | FITTING, HYD | FITTING,HYD,45°ELB,#6MJICX#6MNPT | | | | | |
| 116 | 3 | 0376 | FITTING,HYD | ,TEE, <mark>#</mark> 6MJ | ICX#6FJIC-R | RUNX#6 | MJIC | | |
| 117 | 8 | 0289 | FITTING,HYD | ,STR,#6MJ | ICX#4MNPT | | | | |
| 118 | 6 | 0214 | FITTING,HYD | | | | | | |
| 119 | 4 | 0316 | FITTING, HYD | | | PT | | | |
| 120 | 2 | 0373 | FITTING,HYD | | | | BR | | |
| | • | • | | | | | | | |
| 091-0013 | Added item | ns 29-32,changed pa | rt #s,Qty. re ECN | 16DEC2008 | | ТІТ | LE: | | 11 .1 |
| 082-0068 | C | Quantity was 6 for 8,6 | 6 for 117,4 for 118 | 07NOV2008 | | | | | Hydraulics, |
| 112-0163 | L | Ipdated DWG # & Ite | em 1 Part # | 02SEP2008 | | | | 350 | EXI 600 |
| 082-0058 | | em #7 revised | | 25MAR2008 | | | | | 1 |
| 082-0058 | | | | 240502007 | | DR | AFTED | DenisG | DATE: 02APR2007 |

| Updated DWG # & Item 1 Part # | 02SEP2008 | | 350 EXI 600 | | | |
|-------------------------------|-----------|-------|------------------|-------------------|--|--|
| Item #7 revised | 25MAR2008 | | Denia O | | | |
| Changed as per redlines | 24SEP2007 | | drafted: DenisG | DATE: 02APR2007 | | |
| ISSUED FOR PRODUCTION | 15JUN2007 | | CHECKED: | APPROVED: | | |
| DESCRIPTION | DATE | TESCO | DWG NO: I-840048 | PAGE 6 OF 6 REV 5 | | |

1

0

REV

113-0054

132-003

ECN