



CANRIG DRILLING TECHNOLOGY LTD

PRODUCT BULLETIN NUMBER: 17

DATE: July 13, 1993

SUBJECT: Safety Retention of Electrical Plugs

SERIAL NUMBERS: 002, 004, 006, 007, 008

DISCUSSION: It is necessary to prevent accidental disconnection of the electrical plugs where the service loop cables connect to the top drive unit.

RECOMMENDATION: It is recommended that safety retainers be installed on the subject plugs at all times. On the Camlok plugs on the power cable, use a small bolt to prevent the horseshoe pin from falling out. On the Pyle plugs, use a small wire through one of the holes provided in the retainer nut. Tie the wire so as to prevent the nut from loosening.

INFORMATION:

For further information contact: Field Operations Manager
Canrig Drilling Technology Ltd.
14703 FM 1488
Magnolia, Texas 77354
Phone: 281.259.8887
Fax: 281.259.8158

This page intentionally left blank