

PRODUCT BULLETIN NUMBER: 65

SAFETY ALERT

DATE: 14 March, 2001

SUBJECT: PIPE ENTRAPMENT on TD GUARD

SERIAL NUMBERS: 25,26,27,34,35,39,42,48,50,55,56,66,80,83,96,103,106,121,126,127,130,

131,147,148,151,156,159,163,169,170,171,177

DISCUSSION: While tripping, there is a remote possibility that a stand of pipe could get

stuck behind the Top Drive guard. CANRIG has developed a "deflector plate" up-grade kit, that applies to most Model 1050E-712, 1165E-712, 1050E-

2SP, 1265AC and 1275AC.

To reduce the risk of injury to people or damage to equipment, do not lower

the TD until obstructions (including pipe) have been removed.

RECOMMENDATION:

While tripping out, never lower the Top Drive before the pulled stand of

pipe has been removed from the path of the TD.

To further reduce the risk of an accidental entrapment of the pipe, order AY11137 (deflector plate upgrade kit) from our Field Service Department

and install on Top Drive guard as soon as possible.

<u>INFORMATION:</u>

For further information contact:

Field Operations Manager Canrig Drilling Technology Ltd.

14703 FM 1488

Magnolia, Texas 77354 Phone: 281.259.8887 Fax: 281.259.8158

Top Drive Product Bulletin	
	This page intentionally lett blank
	This page intentionally left blank
	This page intentionally lett blank
	This page intentionally left blank
	This page intentionally lett blank