# **Safety Bulletin**

SB No: SB019 Rev: A Approval Date: April 29, 2005

**Description**: Application of Warning to Casing Drive System

(CDS) Single Joint Elevator Links



#### Introduction

A hazard has been recognized relating to movement of the CDS Single Joint Elevator Links. One method to reduce the risk of drill floor personnel being struck by movement of the CDS Single Joint Elevator Links is to provide constant awareness through application of a warning message.

#### **Components Affected**

The following CDS link part numbers are affected by this bulletin:

| • | 500332 | Link Assembly 10 – 17 ft., DS  |
|---|--------|--------------------------------|
| • | 500333 | Link Assembly 10 - 17 ft., ODS |
| • | 19162  | Link Assembly 8 – 10 ft., DS   |
| • | 19163  | Link Assembly 8 – 10 ft., ODS  |
| • | 16264  | Link Assembly Non-adjustable   |
| • | 540326 | Link Assembly 10 – 17 ft., DS  |
| • | 540327 | Link Assembly 10 – 17 ft., ODS |

### **Action Required**

Apply the following warning in 1-1/2" high red letters (decal or paint stencil) to the outward facing drillers and off-drillers side of the links listed above:

## "STAY CLEAR DURING OPERATION"

Please contact Tesco Corporation at the following email address on issues specific to this bulletin.

Safety\_Technical\_Bulletins@TescoCorp.com

SB019 Rev 0.doc Page 1 of 1