

Change Bulletin

No: CB028

Rev: Draft1

Date: 29 March 2008

Description: Bosch Valve Alternative



Tesco Corporation
6204 – 6A Street SE
Calgary, AB. T2H 2B7
Phone: (403) 692 5700
www.tescocorp.com

BACKGROUND INFORMATION:

According to Engineering Memorandum EM000158, Bosch valves #2062 have been cross-referenced with Vickers BT types due to procurement and availability issues. After a number of retrofits and feed back from the production floor, it was revealed that Vickers retrofits did not perform to expectations. This bulletin is to announce that EM000158 has been discontinued on ECN-111-0070 which essentially disallowed the use of an alternative to the Bosch valve for all hydraulic top drive filter and motor manifolds.

AFFECTED PRODUCT:

The information contained in this bulletin applies for the following Tesco products:

- #720839 - HCI Manifold Assembly
- #14231 - Wire Line Winch, Filter Manifold
- #15148 – Assy, Wireline Winch, c/w Container
- #3175 - HS Motor Manifold Assembly
- #6687 - D2P Filter Manifold, Motor
- #7655 - D6P Filter Manifold, Motor

Reference ECN-s 111-0070, 111-0078, 111-0082 and 111-0084, 111-0083

For existing units in need of a retrofit follow the replacement table below:

Assembly Change		Part 1 change		Part 2 change		Part 3 change		Part 4 change	
From	To	From	To	From	To	From	To	From	To
1410013	720839	1410007	2062	1410008	3158	2953	15300	1410059	2051
1410021	14231	1410022	2062	1410014	10878	4612	10869		
1410024	3175	1410007	2062	19093	16269	1410025(1 kit)	4624 (4pc)	1410059	2051
1410020	6687	1410007	2062	1410014	590116	4612	4613		
1410018	7655	1410007	2062	1410015	590117	4612	10869		

ACTION REQUIRED:

No action required, for information purpose only.

J. Blanes
June 7, 2008

Contact your local TESCO Parts and Service Center for further information regarding this bulletin and or supply of affected components noted above.