

SAFETY BULLETIN SB-005

From: Tesco Products - HSE

Date: May 16, 2003 Models: ECI/EMI

Re: Safety Issues Relating to Pyle\Amphenol High voltage EXE connectors

There have been documented reports of cross communication within the high voltage Pyle\Amphenol EXE rated connectors installed on Electric Tesco Topdrives. There is a risk of personal injury from contact with the connector if an internal failure has occurred. Tesco advises removal of these connectors from all affected equipment. Once the connectors are removed the power cable can be wired directly or can be installed using non-EXE rated camlock connectors. Camlock kits are available for all models of Electric Topdrive upon request.

If there are any questions related to this Safety Bulletin please contact Tesco HSE (403)-233-0757