

PRODUCT BULLETIN NUMBER: 06

EARIG DRILLING TECHNOLOGY LTD

DATE: April 6, 1993

SUBJECT: Handler Rotate and Handler Lock

SERIAL NUMBERS: 002-010

DISCUSSION:

- 1. To avoid injury to personnel, do not use the Handler Rotate with the links tilted significantly of center.
- 2. To avoid inadvertent rotation of the pipe handler, keep the handler LOCKED while drilling. Visually verify the lock pin engagement.
- 3. To avoid in advertent rotation of the pipe handler, always LOCK the handler when using the back-up wrench. Visually verify the lock pin engagement.
- 4. Under most circumstances, the handler can remain LOCKED except while being repositioned. An exception is in allowing the drill string to rotate when hoisting spiral stabilizers in tight hole. Extra caution should be exercised at any time that the handler is unlocked.

INFORMATION:

For further information contact:

Field Operations Manager
Canrig Drilling Technology Ltd.

14703 FM 1488

Magnolia, Texas 77354 Phone: 281.259.8887 Fax: 281.259.8158

Top Drive Product Bulletin	
	This page intentionally lett blank
	This page intentionally left blank
	This page intentionally lett blank
	This page intentionally left blank
	This page intentionally lett blank