



**PRODUCT:** Torqu-Matic Wrench

**DATE:** May 22<sup>nd</sup>, 2008

**SUBJECT:** Leaking fittings within the hydraulic valve banks.

**SERIAL NUMBERS:** All TM Series Wrenches

**DISCUSSION:** It has been brought to Canrig's attention that the BSPP fittings for the HAWE valves that Canrig specifies for use with our valves have been replaced or assembled with the equivalent fittings from various vendors.

**RECOMMENDATION:**

The fittings recommended by Canrig in these locations can NOT be substituted with equivalent fittings, as the equivalent fittings from other suppliers do NOT come with the O-Ring and Retaining Seal. Therefore they require the use of a Douty washer, which is not withstanding the pressures seen in this valve body and they are leaking. If any of your fittings on your valves have the Douty washer installed along with it and are leaking, please contact Canrig and have these replaced with the correct fittings.



DESCRIPTION	ATTRIBUTE VALUE
PRODUCT TYPE	FITTING, INDUSTRIAL TUBE TO STRAIGHT THREAD
TUBE SIZE	18,20mm, 3/4"
TUBE CONNECTION	Male 37 deg Flare
STRAIGHT THREAD SIZE	3/4"
STRAIGHT THREAD CONNECTION	Male BSPP, NBR seal
MATERIAL	Steel, zinc plated
ADDITIONAL DETAIL	
TRADE/BRAND NAME	Triple-Lok
SYNONYM	JIC, 37 deg Flare

**INFORMATION:**

For further information contact:

*For a complete list of all bulletins go to [www.canrig.com](http://www.canrig.com)*

Field Service  
Canrig Drilling Technology Ltd.

14703 FM 1488  
Magnolia, Texas 77354  
Phone: 281.259.8887  
Fax: 281.259.8158

7475 51 Street SE  
Calgary, AB T2C 4L6  
Phone: 403.237.6400  
Fax: 403.233.2667

This page intentionally left blank