## **Change Bulletin**

No: CB049 | Rev: 0 | Date: June 13, 2012

Steel Cable Tugger Line to Replace
Cat Line Tugger During Top Drive Rig Up



Tesco Corporation
5616 – 80th Avenue SE
Calgary, Alberta, Canada T2C 4N5
Tel: 1-877-TESCO-77 (North America)
Tel: 1 (713) 359-7195 (AMSS 24-hour support

Tel: 1 (713) 359-7195 (AMSS 24-hour support) Tel: 1 (713) 359-7295 (International)

Email: <u>bulletins@tescocorp.com</u>

www.tescocorp.com www.tescoparts.com

## **BACKGROUND INFORMATION:**

The rig up procedure in the TESCO Top Drive User Installation Guides includes a note to make use of a "cat line tugger" with rope to assist with installing the Top Drive. Top Drive rentals recently had a technician get hurt from using a cat line tugger that broke and dropped a torque bushing on the technician. Therefore Top Drive rentals is mandating that no cat line tuggers with rope be used when installing Top Drives on any rig; instead, they are to be replaced with a tugger line that uses a steel cable. References to cat line tugger on all Top Drive User Installation Guides need to be changed to suggest the use of a "tugger line".

## **AFFECTED PRODUCTS:**

All TESCO Top Drives. The change is documented and implemented in all TESCO Top Drive User Installation Guides as per ECN-097-0214.

## **ACTION REQUIRED:**

All TESCO Top Drives that are operating in the field or are in the process of being rigged up must replace the cat line tugger with a steel cable tugger line.




Figure 1: Using a steel cable tugger line in place of cat line tugger

Version	Date (D/M/Y)	ECN	Description of changes
Rev 0	13 June 2012	097-0214	Initial release of document